811IHSSF1230



DocumentID

NONCD0002865

Site Name

PIEDMONT TRIAD AIRPORT-AIR CARGO

DocumentType

Site Assessment Rpt (SAR)

RptSegment

1

DocDate

5/7/1991

DocRcvd

2/20/2007

Вох

SF1230

AccessLevel

PUBLIC

Division

WASTE MANAGEMENT

Section

SUPERFUND

Program

IHS (IHS)

DocCat

FACILITY

SUBSURFACE ENVIRONMENTAL INVESTIGATIONS AND CHEMICAL ANALYSIS OF THE AIR CARGO EXPANSION SITE, PIEDMONT TRIAD AIRPORT GREENSBORO, NORTH CAROLINA

Prepared for:

Piedmont Triad Airport Authority
Piedmont Triad International Airport
Greensboro, North Carolina

Trigon Job No. 015-91-036

Prepared by:

Trigon Engineering Consultants, Inc. 313 Gallimore Dairy Road Greensboro, North Carolina



Geotechnical, Environmental, Construction Materials, & Roofing Engineers

EERING CONSULTANTS, INC.

P.O. Box 18846 • Zip 27419 - 8846 • 313 Gallimore Dairy Rd. Greensboro, N.C. 27409 • (919) 668-0093

May 7, 1991

Piedmont Triad Airport Authority

Post Office Box 35005

Greensboro, North Carolina 27425

Attention: Mr. Ted Johnson

Subsurface Environmental Testing with Laboratory Analysis Reference:

Air Cargo Expansion/Waste Disposal Site Piedmont Triad International Airport

Greensboro, North Carolina Trigon Job No. 015-91-036

Dear Mr. Johnson:

Please find enclosed the site investigation report describing the work performed, laboratory results and our recommendations associated with the subject site.

Trigon Engineering Consultants, Inc. appreciates this opportunity to be of assistance to you during this phase of the investigation. Please feel free to contact us if you have any questions concerning this report at your convenience.

Very truly yours,

TRIGON ENGINEERING CONSULTANTS, INC.

J. Scott Pearce

Staff Geologist

Nicholas L. Bogen, PhD, P.G.

Director, Groundwater

Eric N. Johnson, P.E.

Senior Project Engineer

JSP:NLB:ENJ/mb Enclosures

TABLE OF CONTENTS

- 1.0 INTRODUCTION SITE BACKGROUND INFORMATION AND SCOPE OF INVESTIGATION
- 2.0 FIELD ACTIVITIES
 - 2.1 Hand Auger Samples
 - 2.2 Soil Test Borings
 - 2.3 Groundwater Monitoring Wells
- 3.0 HYDROGEOLOGY
- 4.0 LABORATORY RESULTS
 - 4.1 Soil Analysis
 - 4.2 Groundwater Analysis
- 5.0 CONCLUSIONS AND RECOMMENDATIONS

Figures

- 1 Site Location
- 2 Boring Layout Diagram
- 3 Elevation of the Groundwater Table

Tables

- 1 Organic Vapor Soil Screening
- 2 Organic Vapor Monitoring Wells
- 3 Monitoring Well Parameters and Field Measurements
- 4 Chemical Analysis of Soils (Burn Pit)
- 5 Chemical Analysis of Soils (B-3)
- 6 Chemical Analysis of Soils (B-20)
- 7 Chemical Analysis of Soils (B-18, B-19)
- 8 Chemical Analysis of Groundwater

Appendices

- A Soil Test Boring Logs
- B Groundwater Monitoring Well Boring Logs and Well Construction Records
- C Soil and Groundwater Laboratory Analysis

1.0 - SITE BACKGROUND INFORMATION AND SCOPE OF INVESTIGATION

Piedmont Triad Airport is in the process of expanding its air cargo handling area which has involved geotechnical soil borings. While making the geotechnical borings, the odor of petroleum was detected in several locations. Further investigation indicated that some of those locations had been used as burn pits during fire-fighting training exercises. As a result, the Airport Authority undertook additional investigations of soil and groundwater to further determine the nature and extent of the existing conditions. The environmental investigation included additional research on the subject site, six hand auger borings, ten soil test borings, and the installation of five groundwater monitoring wells. Results of these investigations are reported herein.

It is our understanding that the torn down former hangar facility was built by the National Guard in the 1960's and was used for aviation maintenance on small airplanes. Subsequently, Wrangler Aviation used the facility as a maintenance hangar until the mid-1970's. After Wrangler moved out of the facility, the Airport Authority used the building for storage of various types of equipment associated with the airport. In addition, there were two 10,000-gallon underground storage tanks (USTs) for aviation fuels adjacent to the building formerly located in that area. The scope of the investigation included analysis of soils and groundwater. Areas of concern were by the torn down hangar facility, the three burn pits in the subject area, trench drain, construction debris, fill material, reported petroleum spill by the tarmac and groundwater quality.

2.0 - FIELD ACTIVITIES

On April 8, 1991, Trigon mobilized a CME-45 all terrain vehicle (ATV) and a CME 55 truck mounted drill rig to the site. During the period from April 8 to April 16, 1991, there were five areas investigated.

Area number one is adjacent to geotechnical soil boring B-3. Petroleum odors were detected in B-3 and the odors seemed to extend to the interface of the soil and groundwater (figure 2). Six soil test borings were placed around geotechnical boring B-3 and one groundwater monitoring well was installed. Near geotechnical boring B-3 there is a trench drain in the concrete apron, and one hand auger boring was placed by the drain outlet.

Area number two is in the vicinity of geotechnical soil boring B-4 which is beside the burn pits. Two soil test borings, three hand auger borings and one groundwater monitoring well were located adjacent these pits.

Area number three is adjacent to geotechnical soil boring B-20. Petroleum odors were noted in the soil samples while drilling B-20. Two soil test borings and one groundwater monitoring well were placed around B-20.

Area number four is adjacent to geotechnical soil borings B-18 and B-19. The area of concern is located at the base of the fill slope east of B-18 and B-19. Two hand auger borings and one groundwater monitoring well were placed in this area.

The fifth and final area of investigation involved groundwater quality upgradient of the four other areas. An upgradient well was installed adjacent to geotechnical soil boring B-8.

2.1 - Hand Auger Samples

Hand auger borings were made in three areas on site. and during boring activities, the hand auger was decontaminated with a high pressure steam cleaner. The first area included three hand auger borings in the three burn pits by geotechnical boring B-4. One soil sample was taken from each burn pit for analysis of total petroleum hydrocarbons (TPH) by gas chromatography using EPA Methods 3550 and In addition to the TPH sample, one sample taken from burn pit #2 was analyzed for waste characterization by toxic characteristic leachate procedure (TCLP) for RCRA metals. The second area is adjacent to geotechnical soil borings B-18 and B-19. Two hand auger borings were made to a depth of two feet down slope and east from the geotechnical borings B-18 and B-19. Soil samples from both hand auger borings were composited for laboratory analysis for priority pollutant The third area of concern is located west of geotechnical compounds. boring B-3. A trench drain on the concrete apron by the torn down hangar had one hand auger boring made to a depth of four feet. boring was located at the drain outlet. One soil sample was selected for analysis of total petroleum hydrocarbons by EPA Methods 3550 and 5030.

The soil samples selected for laboratory analysis by OVA screening (Table 1) were placed in laboratory prepared jars. The jars were stored in coolers (4°C) for shipment to a North Carolina certified laboratory.

2.2 - Soil Test Borings

Preceding drilling activities at the site, the drill rig and auger tools were decontaminated with a high pressure steam cleaner to prevent the possible introduction of contamination to the site. During the boring activities, the drill rig and tools were decontaminated using a high pressure steam cleaner between each hole to prevent the possibility of cross-contamination of boreholes. Soil samples were retrieved by means of a split-spoon sampling device during drilling. The split-spoon was decontaminated in a solution of Alconox detergent and distilled water between samples and steam cleaned between each boring.

Trigon made ten soil test borings at the site (Figure 2). The soil test borings were advanced with 3-1/4 inch inside diameter hollow-stem augers (HSA) and by driving a split-spoon sampler for collection of soil samples (Appendix A).

The soil test borings were made in three separate areas of the site. The first area of concern is adjacent to geotechnical soil Six soil test borings were performed in this area to depths of approximately 20 feet with split-spoon sampling at 2.5 foot One soil sample per soil test boring was analyzed for TPH intervals. by EPA Methods 3550 and 5030. The second area of concern is adjacent to geotechnical soil boring B-20. Trigon made two soil test borings in the immediate area of B-20 to depths of 10 feet with split-spoon sampling at 2.5 foot intervals. The soil samples retrieved from the borings adjacent to geotechnical boring B-20 were analyzed for TPH by EPA Methods 3550 and 5030. The third area of concern was adjacent to geotechnical soil boring B-4 (burn pits). Two soil test borings were performed in this area to depths of approximately 20 feet with splitspoon sampling at 2.5 foot intervals. The soil samples were retrieved from the borings adjacent to geotechnical boring B-4 were analyzed for TPH by EPA Methods 3550 and 5030.

The soil samples were screened in the field with an OVA for volatile organics which indicate the relative concentration of volatile organic compounds in the soil sample (Table 1). The OVA operates by flame ionization detection (FID). OVA screening for the soil samples revealed 0 to 320 parts per million (ppm). In addition to screening for total volatile organics, the soil samples were screened for methane with an activated charcoal sample probe. The OVA screening for methane ranged from 0 to 90 ppm. After the samples were screened in the field they were placed in laboratory prepared containers for shipment to a North Carolina certified laboratory, Aquachem, Inc., for analysis.

2.3 - Groundwater Monitoring Wells

Trigon constructed five groundwater monitoring wells at the subject site (Figure 2). The drill rig and tools were decontaminated prior to and during drilling activities with a high pressure steam cleaner. During well construction and installation, Trigon personnel wore latex gloves to prevent contamination of the drill tools and the well construction material. The wells were constructed using 6-1/4 inch inside diameter hollow stem augers. The depths of the wells range from 22.0 to 25.0 feet below the ground surface (Appendix B).

The soil samples which were retrieved using a split-spoon sampler during the well boring activities, were screened in the field with an OVA (Table 2). The soil samples screened by the OVA had results of 0 to 500 ppm in wells MW-1, MW-2, MW-3, MW-4 and MW-5.

The groundwater monitoring wells were located adjacent to the five areas of investigation. Monitoring well MW-1 is located by geotechnical soil boring B-8. This monitoring well is an upgradient well, for site background data. MW-2 is located by geotechnical boring B-4. This area is adjacent to the burn pits. MW-3 is located by geotechnical soil boring B-3. A petroleum odor was noted in this area in the upper soil and OVA results indicated contamination extended to the groundwater. MW-4 is located by geotechnical soil boring B-18. This area is where fill material and demolition debris has been

placed. MW-5 is located by geotechnical soil test boring B-20. A petroleum odor was noted in the soil and a groundwater monitoring well was installed in this area.

The groundwater monitoring wells were constructed of 2-inch diameter Schedule 40 PVC pipe and screens with a slot size of 0.010 inch (Appendix B). Once the borings were terminated, the well screen (PVC pipe) was inserted into the soil boring. A solid piece of 2-inch PVC pipe was then screwed into the screen section and extended approximately 2.0 to 2.5 feet above the ground surface. A fine filter sand pack was placed around the screen and extended 2 feet above the top of the screen. A 2-foot sealing layer of bentonite pellets were placed above the sand pack to prevent overlying material from entering the screen area. Next, a grout pack was constructed using portland cement. Finally, a protective stick-up cover with a lock was installed to prevent unauthorized tampering of the groundwater monitoring well.

The groundwater monitoring wells were developed with an oilless pneumatic bladder pump. Between 15 to 35 gallons of water were removed from each well which was equivalent to approximately 4.2 to 20.5 well volumes for each well. Well volume for each well on the day it was developed was approximately 2.0 gallons for MW-1, 2.4 gallons for MW-2, 2.7 gallons for MW-3, 2.7 gallons for MW-4, and 2.5 gallons for MW-5. Field measurements were taken from the wells prior to sampling. The measurements included static water levels, temperature, pH, well volume and OVA screening (Table 3). Prior to sampling of the wells, three well volumes were purged by use of a dedicated laboratory prepared bailer. At groundwater monitoring well MW-4, an equipment blank was made on the dedicated bailer prior to purging and sampling. The purpose of the equipment blank is to verify field sampling practices and laboratory analytical procedures. The water samples and equipment blanks were placed in laboratory prepared containers which were screened with an OVA for volatile organics. The water samples collected were analyzed for TPH by EPA Method 3550 and 5030, volatile organics by EPA Method 601 and 602, and total RCRA metals. The water samples collected for metals were filtered in the field with a 0.45 micron filter. The purpose of filtering the water sample was to remove some suspended particles that could interfere with the metals The samples were packaged in coolers with ice packs (4° C) for shipment to Aquachem, Inc. for analysis.

3.0 - HYDROGEOLOGY

The site is located in the Carolina Slate Belt and in the Piedmont physiographic province of North Carolina. The unconsolidated section consists of fill material on top of alluvial material which rests on residual material. The alluvial material is 15 to 22 feet thick. It is a blue grey sandy silt. Below the alluvial material is a residual material. It is a tan brown sandy silt. Partially weathered rock was encountered in MW-4 at a depth of approximately 15 feet. The underlying bedrock at the site consists of a metamorphosed gabbro and/or diorite rock according to the 1985 Geologic Map of North Carolina.

The groundwater depths at the site varied from 6.9 feet (MW-3) to 11.7 feet (MW-1) beneath the ground surface (Table 3). Relative elevations for the monitoring wells with respect to a bench mark established on site were measured at the top of the concrete pad surrounding the protective stick-up cover (Figure 3). Groundwater table elevations indicate that the groundwater is migrating in a northeasterly direction on the site (Figure 3). The groundwater appears to be discharging downslope to the east of MW-4 in a swampy area. Groundwater flow rates were not determined.

4.0 - LABORATORY ANALYSIS

4.1 - Soil Analysis

The soil samples retrieved adjacent to geotechnical soil boring B-4 were analyzed for total petroleum hydrocarbons (TPH). In addition to the TPH analysis, one sample was analyzed for leachable metals. The laboratory results for the soil, as reported by Aquachem, Inc., revealed petroleum hydrocarbons in soil samples from BP-1, BP-2, BP-3, STB-1, and STB-2 (Table 4). The sample results ranged from a low of 11 parts per million (ppm) to a high of 14,302 ppm which were similar to fuel oils. The sample analysis for gasoline revealed 1 part per million (ppm) in BP-3, STB-1, STB-2, STB-3 and 971 ppm in BP-1. The soil sample from MW-2 did not reveal petroleum hydrocarbons above detection limits. In addition to the TPH samples, one sample (BP-2) was analyzed for leachable metals and none were detected.

The soil samples retrieved near geotechnical boring B-3 were analyzed for total petroleum hydrocarbons, and one sample was analyzed for leachable metals. The seven soil samples taken adjacent to geotechnical soil boring B-3 revealed less than 10 ppm for fuel oils (Table 5). Analysis for gasoline indicated two of the soil test borings, B-3W and MW-3 contained 9 and 54 ppm, respectively. The soil sample which was collected from B-3S was also tested for metals. The analysis did not reveal any metals above detection limits.

The soil samples from the area adjacent to geotechnical boring B-20 were analyzed for total petroleum hydrocarbons. The laboratory analysis, as reported by Aquachem, Inc., did not reveal any petroleum hydrocarbons above detection limits (Table 6).

The soil sample taken by geotechnical boring B-18 and B-19 taken at the base of the fill slope in the swampy area was analyzed for priority pollutant compounds. The analysis for metals revealed chromium at 4.3 milligrams per liter (mg/l), copper at 22.6 mg/l, lead at 13.3 mg/l, nickel at 3.95 mg/l, and zinc at 27.5 mg/l (Table 7). In addition to the metals identified, benzene was present at 239 micrograms per kilogram (μ g/kg) and toluene at 246 μ g/kg. The soil sample analyzed for TPH near (TD-HA1) geotechnical soil boring B-3 adjacent to the torn down hangar did not reveal petroleum hydrocarbons above detection limits.

4.2 - Groundwater Analysis

The groundwater samples and equipment blank were analyzed for total petroleum hydrocarbons, volatile organic compounds and total RCRA metals. The analysis revealed substances which are above North Carolina water quality standards (NCWQS) (Appendix C). The water samples analyzed for metals did not contain any compounds above detection limits. The analysis for total petroleum hydrocarbons revealed petroleum hydrocarbons in monitoring wells MW-1 through MW-5 (Table 8). Concentrations ranged from less than 0.1 milligrams per liter to 5 milligrams per liter (mg/l). Benzene was present in monitoring wells MW-3 and MW-4 above state standards. compounds which were identified in MW-3 above state standards are tetrachloroethene and 1,4-dichlorobenzene. One compound which all wells shared in common was chloroform. The amount detected range from 8 μ g/1 to 43 μ g/1. The chloroform could be a breakdown product of tetrachloroethene or dichlorobenzene coming in contact with organic material in the fill. At every monitoring well location, fill material was encountered. Monitoring well MW-4 had an equipment blank performed on its bailer prior to sampling. The equipment blank did identify toluene and methylene chloride above detection limits. The methylene chloride was additionally present in MW-5. It is not a primary contaminant. It is a suspected laboratory artifact.

5.0 - CONCLUSIONS AND RECOMMENDATIONS

The majority of the sample locations tested revealed evidence of petroleum at the hydrocarbons site. The impact is present in the soil and in the groundwater. Existing data from both field and laboratory data indicate the following:

- 1. The area adjacent to geotechnical soil boring B-4 (burn pit) did contain petroleum hydrocarbons in the soil. The highest concentrations were noted in burn pit number 1. The groundwater revealed toluene and chloroform. The concentration of chloroform exceeds state water quality standards but toluene is below standards. The vertical and horizontal extent of the soil impact is not completely defined and extent of groundwater impact is not fully known. Due to the high concentrations of petroleum hydrocarbons in the soils, it is likely that groundwater problem will persist and may increase.
- 2. The soil samples retrieved adjacent to geotechnical boring B-3 indicate limited impact to the soil. The areal extent of the impact is fairly well defined. Groundwater in the area contains benzene, tetrachloroethene, chloroform and 1,4 dichlorobenzene above state standards. Toluene is very close to state groundwater quality standards. The horizontal extent of the groundwater impact is not known at this time. Other chemicals were also identified but they were below state water quality standards.


- 3. The groundwater at the base of the fill slope by geotechnical borings B-18 and B-20 exceeds state limits for benzene. The groundwater in MW-4 by B-18 revealed benzene and chloroform above state standards. The groundwater beneath the fill slope could be impacting the soil in HA-1 and HA-2.
- 4. The area around geotechnical soil boring B-20 does not appear to have petroleum hydrocarbon in the soil. Chloroform exceeds state groundwater limits.
- 5. The groundwater around geotechnical boring B-8 (MW-1) revealed a petroleum hydrocarbon blend similar to fuel oil. Chloroform was also present in the groundwater and exceeds the state groundwater quality standards. The source of the oil is not known, but is apparently southwest and upgradient of MW-1.
- 6. No problem was noted by the trench drain (TD-HA1) in the soils.
- 7. The hydraulic gradient, as determined from the static water levels for the five monitoring wells, indicates that the ground-water is migrating beneath the study area in a northeasterly direction. The full extent of groundwater impact is not known at this time.


Trigon recommends the following items be performed as further investigation:


- 1. Determine the full extent of the groundwater impact as described in this report. Monitoring wells MW-3 and MW-4 both contained benzene above state standards. Additional investigation is needed in these areas. Monitoring well MW-1 is the upgradient well. Fuel oils are present in the groundwater at this location. Further investigation is needed to determine the source of the fuel oils.
- 2. Resample the existing groundwater monitoring wells in three months. This information will help determine the rate contaminant concentration change.
- 3. Determine the extent of petroleum hydrocarbon in the soil at the burn pits.
- 4. Determine the extent of soil impact in the area east of geotechnical soil borings B-18 and B-19.

FIGURES

11







TABLES

TRIGON ENGINEERING CONSULTANTS, INC. SUMMARY OF OVA MONITORING TABLE 1

Job Name: Air Cargo Expansion

Job Location: Greensboro, North Carolina Job No: 015-91-036

Date: April 10, 1991

Boring	Sample Number	Depth (feet)	OVA ¹ (Field) (ppm) ² Normal/Methane Tip	Comments
BP-1	1	0 - 1.0	180-360/4	Odor
	2	1.0 - 2.0	320/20	Odor
	3	2.0 - 3.0	220/0	Odor - S.T. 6:00 P.M. TPH
	4	3.0 - 4.0	200/0	Odor
	5	4.0 - 5.0	260/0	Odor
BP-2	11	0 - 1.0	30/	Odor
	2	1.0 - 2.0	120/	Odor - Comp TCLP
	3	2.0 - 3.0	180/	Odor
	4	3.0 - 4.0	88/	Odor
	5	4.0 - 5.0	140/	Odor
	6	5.0 - 6.0	130/	Odor - S.T. 6:10 P.M. TPH
BP-3	1	0 - 1.0	10	
	2	1.0 - 2.0	8.5	S.T. 6:15 P.M. TPH
	3	2.0 - 3.0	3	
	4	3.0 - 4.0	.75	
	5	4.0 - 5.0	.80	
	6	5.0 - 6.0	.60	
STB-2 BURN PIT#2	1	1.0 - 2.5	0/0	No odor
	2	3.5 - 5.0	0/1	No odor
	3	6.0 - 7.5	0/1	No odor
	4	8.5 - 10.0	0/4	No odor
	5	11.0 - 12.5	0/3	No odor
ļ .	6	13.5 - 15.0	4/1	No odor
	7	16.0 - 17.5	0/0	No odor
	8	18.5 - 20.0	6/4	No odor - S.T. 5:52 P.M TPH - Top of Bedrock 20.0'

TRIGON ENGINEERING CONSULTANTS, INC. SUMMARY OF OVA MONITORING TABLE 1 - Continued

Job Name: Air Cargo Expansion

Job Location: Greensboro, North Carolina

Job No: 015-91-036 Date: April 10, 1991

	Sample		OVA ¹ (Field)	
Boring	Number	Depth (feet)	(ppm) ² Normal/Nethane Tip	Comments
STB-1 BURN PIT #3	1	1.0 - 2.5	0/0	No odor
	2	3.5 - 5.0	0/0	No odor
	3	6.0 - 7.5	0/.5	No odor
	4	8.5 - 10.0	0/0	No odor
	5	11.0 - 12.5	0/0	No odor
	6	13.5 - 15.0	0/0	No odor
	7	16.0 - 17.5	200/90	Slight odor - S.T. 3:45 PM
	8	18.5 - 20.0	9/4	No Odor Top of Bedrock 20.0'
B-3W	1	1.0 - 2.5	0/10	No odor
	2	3.5 - 5.0	0/0	No odor
	3	6.0 - 7.5	0/0	No odor
	4	8.5 - 10.0	50/30	No odor
	5	11.0 - 12.5	100/30	Odor
	6	13.5 - 15.0	20/20	Odor
	7	16.0 - 17.5	25/20	Odor
	8	18.5 - 20.0	0/0	No odor
B-3N	1	1.0 - 2.5	0/10	No odor
	2	3.5 - 5.0	0/0	No odor
	3	6.0 - 7.5	0/0	No odor
	4	8.5 - 10.0	0/0	No odor
	5	11.0 - 12.5	0/0	No odor
	6	13.5 - 15.0	1/1	No odor
	7	16.0 - 17.5	1.5/1	No odor
	8	18.5 - 20.0	2/2	No odor

TRIGON ENGINEERING CONSULTANTS, INC. SUMMARY OF OVA MONITORING TABLE 1 - Continued

Job Name: Air Cargo Expansion

Job Location: Greensboro, North Carolina

Job No: 015-91-036 Date: April 8, 1991

Boring	Sample Number	Depth (feet)	OVA ¹ (Field) (ppm) ² Normal/Methane:Tip	Comments
B-3S	1	1.0 - 2.5	5/20	No odor
	2	3.5 - 5.0	0/20	No odor
	3	6.0 - 7.5	10/20	No odor
	4	8.5 - 10.0	50/40	Slight odor
	5	11.0 - 12.5	60/30	Slight odor
	6	13.5 - 15.0	70/30	Slight odor
	7	16.0 - 17.5	40/20	No odor - S.T. 2:30 P.M.
	8	18.5 - 20.0	20/25	Slight Odor
B-3E	1	1.0 - 2.5	1.5/10	No odor
	2	3.5 - 5.0	0/0	No odor
	3	6.0 - 7.5	0/0.5	No odor
	4	8.5 - 10.0	0/0	No odor
	5	11.0 - 12.5	0/0.5	No odor
	6	13.5 - 15.0	1.5/1.5	No odor
	7	16.0 - 17.5	2/4	No odor - S.T. 2:30 PM TPH
	8	18.5 - 20.0	2/2.5	No odor
B-3WEX	1	1.0 - 2.5	0/0	No odor
	2	3.5 - 5.0	0/0	No odor
	3	6.0 - 7.5	0/0	No odor
	4	8.5 - 10.0	0/0	No odor
	5	11.0 - 12.5	0/0	No odor
	6	13.5 - 15.0	0/0	No odor
	7	16.0 - 17.5	0/0	No odor - S.T. 4:00 PM TPH
	8	18.5 - 20.0	3/10	No odor

TRIGON ENGINEERING CONSULTANTS, INC. SUMMARY OF OVA MONITORING TABLE 1 - Continued

Job Name: Air Cargo Expansion

Job Location: Greensboro, North Carolina

Job No: 015-91-036 Date: April 10, 1991

Boring	Sample Number	Depth (feet)	OVA ¹ (Field) (ppm) ² Normal/Methane Tip	Comments
B-20N	1	1.0 - 2.5	0/10	No odor
	2	3.5 - 5.0	1/8	No odor
	3	6.0 - 7.5	3/12	No odor
	4	8.5 - 10.0	10/4	No odor - S.T. 1:10 P.M. Top of Bedrock 10.0 feet
B-20S	1	1.0 - 2.5	0/10	No odor
	2	3.5 - 5.0	0/0	No odor
	3	6.0 - 7.5	.5/1	No odor
	4	8.5 - 10.0	1/2	No odor - S.T. 2:15 P.M. Top of Bedrock 10.0 feet

Notes: 1Organic Vapor Analyzer (OVA) measures the concentration of organic vapors in the air.

²ppm = parts per million

S.T. = Sample Time

TRIGON ENGINEERING CONSULTANTS, INC. SUMMARY OF OVA MONITORING TABLE 2

Job Name: Air Cargo Expansion

Job Location: Greensboro, North Carolina

Job No: 015-91-036 Date: April 8, 1991

	over animal planted and a Table 3	Date:	ADIII 0, 1991	
Boring	Sample Number	Depth (feet)	OVA ¹ (Field) (ppm) ² Normal/Methane Tip	Comments
MW-1	11	1.0 - 2.5	0	
	2	3.5 - 5.0	.2	
	3	6.0 - 7.5	0	
	4	8.5 - 10.0	0	
	5	11.0 - 12.5	0	
	6	13.5 - 15.0	0	
	7	16.0 - 17.5	0	
	8	18.5 - 20.0	0	
	9	21.0 - 22.5	0	
	10	23.5 - 25.0	.2	
MW-2	1	1.0 - 2.5	0	
	2	3.5 - 5.0	0	
	3	6.0 - 7.5	0	
	4	8.5 - 10.0	0	
	5	11.0 - 12.5	0	
	6	13.5 - 15.0	0	
	7	16.0 - 17.5	12	S.T. 4:11 P.M.
	8	18.5 - 20.0	0	
	9	21.0 - 22.5	.4	
MW-3	1	1.0 - 2.5	0/8	No odor/6"
	2	3.5 - 5.0	15/10	No odor/12"
	3	6.0 - 7.5	100/50	Slight odor/10"
	4	8.5 - 10.0	150/30	Odor/12"
	5	11.0 - 12.5		No recovery
· · · · · · · · · · · · · · · · · · ·	6	13.5 - 15.0	300/100	Odor/8"
	7	16.0 - 17.5	30/20	No odor/8"
	8	18.5 - 20.0	10/10	No odor/6"
	9	21.0 - 22.5	1/3	No odor/10"
	10	23.5 - 25.0	1/2	No odor Res./12"

TRIGON ENGINEERING CONSULTANTS, INC. SUMMARY OF OVA MONITORING TABLE 2 - Continued

Job Name: Air Cargo Expansion

Job Location: Greensboro, North Carolina

Job No: 015-91-036 Date: April 8, 1991

Boring	Sample Number	Depth (feet)	OVA ¹ (Field) (ppm) ² Normal/Methane Tip	Comments
MW-4	1	1.0 - 2.5	0	Asphalt
	- 2	3.5 - 5.0	0.8	Asphalt
	3	6.0 - 7.5	0.8	Asphalt
	4	8.5 - 10.0	8.5/4.5	Asphalt
	5	11.0 - 12.5		No Recovery
	6	13.5 - 15.0	77/85	
	7	16.0 - 17.5	2.5/3.5	
	8	18.5 - 20.0	9/4.5	
MW-5	1	1.0 - 2.5	0	
	2	3.5 - 5.0	0.2	
	3	6.0 - 7.5	4.5/8	
	4	8.5 - 10.0	50/95	
	5	11.0 - 12.5	9.5/4.5	
	6	13.5 - 15.0	20-50/28	
	7	16.0 - 17.5	500/250	S.T. 10:00 A.M.
	8	18.5 - 20.0	30/30	
	9	21.0 - 22.5	2.5	
	10	23.5 - 25.0	.6	

Organic Vapor Analyzer (OVA) measures the concentration of Notes: organic vapors in the air.

2ppm = parts per million S.T. = Sample Time

TABLE 3

Field Measurements - Groundwater Monitoring Wells Piedmont Triad International Airport Air Cargo Expansion Greensboro, North Carolina 015-91-036

April 15 and 16, 1991*	MW-1	MW-2	MW-3	MW-4	MW-5
pH Beginning	5.5	5.3	6.2	6.2	6.3
pH Final	5.6	5.5	6.3	6.2	6.5
Temperature °C Beginning	17.5	17.7	14.6	16.9	14.4
Temperature °C Final	17.2	18.8	15.3	16.0	14.7
Surface Elevation (feet)	895.3	893.0	889.3	872.4	887.2
Static Water Level ¹ (feet)	484.7	885.7	882.4	863.7	877.3
Depth to Water (feet)	10.6	7.3	6.9	8.7	9.9
Total Depth (feet)	24.5	23.0	24.5	20.5	25.0
Well Volume (gallon)	2.0	2.4	2.7	2.7	2.5
OVA Screening (ppm)	О	0	4.0	0	4.0

¹Static water levels measured on May 4, 1991 *Date field measurements taken.

OVA - Organic Vapor Analyzer

ppm - Parts Per Million

TABLE 4

Piedmont Triad International Airport Air Cargo Expansion Greensboro, North Carolina 015-91-036

Sample Location	Analysis Method EPA 3550*	Analysis Method EPA 5030*
BP-1: 2.0 - 3.0 feet	14,302	971
BP-2: 5.0 - 6.0 feet	2,044	221
BP-3: 1.0 - 2.0 feet	40	<1
STB-1: 16.0 - 17.5 feet	10	<1
STB-2: 18.5 - 20.0 feet	11	<1
MW-2: 16.0 - 17.5 feet	<10	<1

^{*}Sample results reported in milligrams per kilogram

TABLE 5

Piedmont Triad International Airport Air Cargo Expansion Greensboro, North Carolina 015-91-036

Sample Location	Analysis Method EPA 3550*	Analysis Method EPA 5030*
B-3S	<10	<1
B-3W	<10	9
B-3N	<10	<1
B-3E	<10	<1
B-3W Extension	<10	<1
MW-3	<10	54
STB-3	<10	<1

^{*}Sample results reported in milligrams per kilogram

TABLE 6

Piedmont Triad International Airport Air Cargo Expansion Greensboro, North Carolina 015-91-036

Sample Location	Analysis Method EPA 3550*	Analysis Method EPA 5030*
B-20N	<10	<1
B-20S	<10	<1
MW-5	<10	<1

^{*}Sample results reported in milligrams per kilogram

TABLE 7

Piedmont Triad International Airport Air Cargo Expansion Greensboro, North Carolina 015-91-036

Sample Location	Parameter	Concentration
HA-1, HA-2	Chromium	4.3 mg/l
	Copper	22.6 mg/l
	Lead	13.3 mg/l
	Nickel	3.95 mg/l
	Zinc	27.5 mg/l
	Benzene	239 μg/kg
	Toluene	246 μg/kg

mg/l - milligrams per liter

 μ g/kg - micrograms per kilogram

TABLE 8

Piedmont Triad International Airport Air Cargo Expansion Greensboro, North Carolina 015-91-036

Parameter	MW-1	MW-2	MW-3	MW-4	MW-5	MW-4 Eq Blk	NCWQS
TPH - EPA 3550 ¹	5.0	3.0	<1.0	1.0	1.0	BQL	
TPH - EPA 50501	<0.1	<0.1	4.0	<0.1	<0.1	BQL	
Toluene ²	BQL	BQL	988	289	248	247	1,000
Benzene ²	BQL	BQL	356	233	BQL	BQL	1
1,2-Dichlorobenzene ²	BQL	BQL	189	BQL	BQL	BQL	620
1,4-Dichlorobenzene ²	BQL	BQL	576	BQL	BQL	BQL	1.8
Tetrachloroethene ²	BQL	BQL	363	BQL	BQL	BQL	Detec- tion
Xylene ²	BQL	BQL	286	BQL	BQL	BQL	400
Methylene Chloride ²	BQL	BQL	BQL	BQL	610	578	5
Chloroform ²	41	34	38	43	8	8	.19

NOTES


Units are milligram per liter (mg/l)
 Units are micrograms per liter (μg/l)

TPH - Total Petroleum Hydrocarbons

MW - Monitoring Well

NCWQS - North Carolina Water Quality Standard

APPENDIX A



BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. 1.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE


50 % ROCK CORE RECOVERY

LOSS OF DRILLING WATER



TEST BORING RECORD

BORING NO. $\frac{\text{STB-1}}{\text{DATE DRILLED}} \frac{04/10/91}{015-91-036}$ JOB NO.




BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. 1.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE

50 % ROCK CORE RECOVERY

■ LOSS OF DRILLING WATER




TEST BORING RECORD

BORING NO. STB-2

DATE DRILLED 04/10/91

JOB NO. 015-91-036




BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. 1.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE


50 % ROCK CORE RECOVERY

■ LOSS OF DRILLING WATER



TEST BORING RECORD

BORING NO. $\frac{B-3 \text{ W Ext}}{04/09/91}$ JOB NO. $\frac{015-01-036}{015-01}$




BORING AND SAMPLING MEETS ASTM 0-1586 CORE DRILLING MEETS ASTM 0-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. 1.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE

50 % ROCK CORE RECOVERY

LOSS OF DRILLING WATER




TEST BORING RECORD

BORING NO. STB-3

DATE DRILLED 04/11/91

JOB NO. 015-91-036




BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. 1.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE

50 % ROCK CORE RECOVERY

LOSS OF DRILLING WATER




TEST BORING RECORD

BORING NO. B-3 N

DATE DRILLED 04/08/91

JOB NO. 013-91-036




BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. I.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE


50 % ROCK CORE RECOVERY

LOSS OF DRILLING WATER



TEST BORING RECORD

BORING NO. B-3 S DATE DRILLED 04/09/91 JOB NO. 015-91-036



BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. 1.D. SAMPLER 1 FT. .

undisturbed sample


50 % rock core recovery

Loss of drilling water



TEST BORING RECORD

BORING NO. B-3 E DATE DRILLED 04/09/91 JOB NO. 015-91-036




BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. 1.D. SAMPLER 1 FT.

undisturbed sample


50 % rock core recovery

Loss of Drilling Water



TEST BORING RECORD

BORING NO. B-3 W DATE DRILLED 04/08/91 JOB NO. 015-91-036




BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. 1.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE


50 % ROCK CORE RECOVERY

LOSS OF DRILLING WATER



TEST BORING RECORD

BORING NO. B-20 N DATE DRILLED 04/10/91 JOB NO. 015-91-036



BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. I.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE

50 % ROCK CORE RECOVERY


■ LOSS OF DRILLING WATER



TEST BORING RECORD

BORING NO. B-20 S DATE DRILLED 04/10/91 JOB NO. 015-91-036

APPENDIX B




BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. I.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE

| 50 % ROCK CORE RECOVERY

■ LOSS OF DRILLING WATER



TEST BORING RECORD

BORING NO. MW-1

DATE DRILLED 04/09/91

JOB NO. 015-91-036

NORTH CAROLINA DEPARTMENT OF NATURAL RESOURCES AND COMMUNITY DEVELOPMENT DIVISION OF ENVIRONMENTAL MANAGEMENT - GROUNDWATER SECTION
P.O. 80X 27687 - RALEIGHLAG. 27611, PHONE (919) 733-6083

WEL	T CC	TRNC	RUC'	TION	REC	ORD
-----	------	------	------	------	-----	-----


Revised 11/84

FOR OFFICE USE ONLY
Senal No
Long Pc
GW-1 Ent

		Header E	it GW-1 Ent	
DRILLING CONTRACTOR TRIGON ENGINEERING CONSULTANTS	, INC.			
DRILLER REGISTRATION NUMBER 813	STATE WELL CONSTRUCTION PERMIT NUMBER: 40-0949-WM-0336			
WELL LOCATION: (Show sketch of the location below)				
Nearest Town: Greensboro, NC	County:	Guilford	County	
(Road, Community, or Subdivision and Lot No.)	- Deoth	•	DRILLING LCG	
OWNER Piedmont Triad Airport Authority	MW		Formation Description	
ADDRESS P.O. Box 35005			Grass and Topsoil	
Greensboro, North Carolyna No. 1 27425	0.4	3.0 -	Stiff Red Orange and White	
City or Town State Zip Code , DATE DRILLED 04/09/91 USE OF WELL Monitoring			Medium to Fine Sandy Silty CLAY-Trace Roots-Fill	
. TOTAL DEPTH 24.5 CUTTINGS COLLECTED \square Yes \square No	3.0		Soft Brown Black and Red	
DOES WELL REPLACE EXISTING WELL? Yes No			Slightly Micaceous Silty CLAY	
STATIC WATER LEVEL: 14.0 FT. Dabove TOP OF CASING.	0 0 1			
TOP OF GASING IS FT. ABOVE LAND SURFACE	8.0 1		Firm Brown Orange Clayey SILT Damp-Fill	
YIELD (gpm): N/A METHOD OF TEST N/A	10.5 1		Stiff Brown and Grey Slightly	
. WATER ZONES (death):			Gravelly Coarse to Fine Sandy	
CHLORINATION: Type NA . Amount NA	13.0 2		Clayey SILT-Fill Stiff to Very Stiff Brown	
). CASING:			ce is needed use back of form. (Con't)	
Wall Thickness O.O Depth Diameter or Weignt/Ft. Material			OCATION SKETCH	
From To To 5.5 _ Ft 2 SCH40 PVC	(Show direc	tion and dis	stance from at least two State Roads.	
Frem To Ft	of other ma	ap reference	points)	
From To Ft	310	ر کرانجر کہ		
. GROUT: Depth Material Method	ndship/Ch	ENSBORO HIGH	SOINT SOUNT	
From 0.0 To 5.5 Ft. Portland Slue		WINSTON SALE	M // Significant of the second	
From To Ft			Hors.	
SCREEN:	Endship 7	× (898		
9.5 Depth 24.5 Diameter Slot Size Material	0-890			
9.5 24.5 Dameter Slot 324 Material (1975) State of the st		acon .		
From To Ft in in		6:0		
From To Ft in in	3 7	5		
Gravel Pack:		5 5	0 1 (090)	
Depth Size Material From 7.5 To 24.5 Ft. Fine Filter Sand		$-\widetilde{i}$	BM (389)	
From To Ft. Bentonite Seal From 5.5 to 7.5.	710/	11/		
LOO HEREBY CERTIFY THAT THIS WELL WAS CONSTRUCTED	IN ACCORDANG	CE WITH 15	NCAC 2C WELL CONCENTION	
STANDARDS, AND THAT A COPY OF THIS RECORD HAS BEEN PAC	שאו סו כשטענ	METT OMVE	ia.	
y orolly	easel		05/02/91	

SIGNATURE OF CONTRACTOR OR AGENT

Submit original to Division of Environmental Management and copy to well owner.



BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. 1.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE

50 % ROCK CORE RECOVERY

LOSS OF DRILLING WATER



TEST BORING RECORD

BORING NO. MW-2

DATE DRILLED 04/09/91

JOB NO. 015-91-036

NORTH CARGUNA DEPARTMENT OF NATURAL RESOURCES AND COMMUNITY DEVELOPMENT DIVISION OF ENVIRONMENTAL MANAGEMENT - GROUNDWATER SECTION P.O. BOX 27887 - RALEIGHLNLC, 27811, PHONE (919) 733-6083

WELL	CONST	TRUCTION	RECORD
------	-------	----------	--------

-1 Revised 11/84


	FOR OFFICE USE ONLY
Quad. No.	Senal No.
Lat.	Lang Pe
	GW-1 Ent

DATE

		Head	er Ent GW-1 Ent
PRILLING CONTRACTOR TRIGON ENGINEERING CONSULTANTS,	INC.	<u> </u>	
DRILLER REGISTRATION NUMBER813	STA		CONSTRUCTION BER: _40-0949-WM-0336
WELL LOCATION: (Show sketch of the location below)			
Nearest Town: Greensboro	Caunty	Guilf	ord County
(Road, Community, or Suddivision and Lot No.)	- 00	epth	DRILLING LOG
OWNER Piedmont Triad Airport Authority	FramM	W-2 To	Formation Description
P.O. Box 35005	0.0	0.3	Grass and Topsoil
Greensboro, NC (Street of Houte No.) 27425	0.3	3.0	Stiff Orange Brown Slightly
City or Town State Zio Code .	`. 		Clayey Medium to Fine Sandy
DATE DRILLED 04/09/91 USE OF WELL MODITORING TOTAL DEPTH 23' CUTTINGS COLLECTED Yes X No	3.0	15.5	SILT-Fill Firm and Soft Red Brown and
DOES WELL REPLACE EXISTING WELL? Yes X No			Orange Fine Sandy Clayey SILT-
			Fill
STATIC WATER LEVEL: 11.3' FT. II above TOP OF CASING. TOP OF CASING IS 2.5 FT. ABOVE LAND SURFACE	15.5	18.0	Firm Green Slightly Clayey
YIELD (gpm): N/A METHOD OF TEST N/A			Medium to Fine Sandy SILT-
WATER ZONES (dectri): 8.8	18.0	20.5	Alluvial Firm Blue Grey Silty CLAY-
	10.0	20.3	
CHLORINATION: Type N/A Amount N/A	20.5	22.5	Alluvial Firm Blue Grey Clayey SILT-
. CASING: Wall Thickness Death Diameter or Weignt/Ft. Material	1:	f additional	space is needed use back of form.Alluvia
Ceom Diameter of Weight/Ft. Material From 0 To 8 Ft. 2 SCH40 PVC			LOCATION SKETCH
From ToFt	(Show o	direction and	d distance from at least two State Roads.
FromTo	310	/1/ 7	and district
	endship/Ch		
Depth Material Method	رُبُ لِيرُهُ	CREENSBORD	MIGH POINT
From 0 To 4 Ft. Portland Slue	بماريز	AIRP	
FromToFt	riendship		303
SCREEN:		<u></u>	(598)
Depth Diameter Slot Size Material		890	
From 8 To 23 Ft. 2 in. 0.010in. PVC	$(\mathcal{L}_{\mathcal{L}})$		8 3
From To Ft in	\$ 17)		
GRAVEL PACK:	7//	155 5	890
Depth Size Material			BM () (2620) (2)
From 6 To 23.0 Ft. Fine Filter Sand		بربر	389
From To Ft. Bentonite Seal From 4.0' tp 6.0'	710	The,	-500
I DO HEREBY CERTIFY THAT THIS WELL WAS CONSTRUCTED, STANDARDS, AND THAT A COPY OF THIS RECORD HAS BEEN PRO	IN ACCERC DVC TO TO	THE WELL O	H 15 NCAC 2C. WELL CONSTRUCTION WNER. 05/02/91

SIGNATURE OF CONTRACTOR OR AGENT

Submit original to Division of Environmental Management and copy to well owner.



BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. I.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE

50 % ROCK CORE RECOVERY

LOSS OF DRILLING WATER



TEST BORING RECORD

BORING NO. MW-3

DATE DRILLED 04/10/91

JOB NO. 015-91-036

NORTH CAROLINA DEPARTMENT OF NATURAL RESOURCES AND COMMUNITY DEVELOPMENT DIVISION OF ENVIRONMENTAL MANAGEMENT - GROUNDWATER SECTION
P.O. 80X 27687 - RALEIGHLING, 27611, PHONE (919) 733-5083

WELL	CONS	TRUC	TION	RECO	RD
------	------	------	------	------	----


Revised 11/84

	FOR OFFICE USE ONLY
Quad. No	Senal No.
Lat.	Lang Pc
Basin Code	
Header Ent	GW-1 Ent

		Heade	r Ent	GW-1 Ent
PRILLING CONTRACTOR TRIGON ENGINEERING CONSULTANTS	, INC.	L		
DRILLER REGISTRATION NUMBER813	SIA		CONSTRUCTIO	
STILLE THE THE TOTAL TOT	- PER	MIT NUME	BER: <u>40-094</u>	9-WM-0336
WELL LOCATION: (Show sketch of the location below)				
Nearest Town: Greensboro	_ County:	Guilfo	ord County	·
(Road, Community, or Subdivision and Lot No.)	- <u>D</u> e	eoth	(DRILLING LOG
OWNER Piedmont Triad Airport Authority	Franky-	-3 To	For	mation Description
P.O. Box 35005	0.0	6.0	Firm Brow	n Orange and Red
Greensboro, NC (Street or Route No.) 27425				Fine Sandy Clayey
City or Town State Zip Code			Fill	
DATE DRILLED 04/10/91 USE OF WELL Monitoring	6.0	16.0	Soft Brow	n Slightly Fine Sa
. TOTAL DEPTH 24.5 CUTTINGS COLLECTED $ ext{M}$ Yes $ ext{\square}$ No			Clayey SI	
DOES WELL REPLACE EXISTING WELL? Yes X No	16.0	18.0	Soft Grey	Slightly Clayey F.
STATIC WATER LEVEL: 14.0 FT. Q above TOP OF CASING. TOP OF CASING IS 2.3 FT. ABOVE LAND SURFACE				T-Alluvial
	18.0	23.0		tiff Blue Grey and
YIELD (gpm): N/A METHOD OF TEST N/A				e Sandy Clayey SIL
WATER ZONES (deoth):	23.0	25.0	Alluvial	
			Firm White Residual	e Blue and Green Si
CHLORINATION: Type N/A Amount N/A	. '		Residual	·
D. CASING: Wall Thickness		additional	space is needed	t use back of form.
Depth Diameter or Weight/Ft. Material PVC	=====		LOCATION SK	
	(Show d	direction and	distance from	at least two State Roads,
FremToFt	or other	r man refere	inca points)	/ 139
FromToFt	319 - 1	شغر کس		
. GRCUT: Depth Material Method	indship/Ch	CREENSBORO		
From 0.0 To 5.5 Ft. Portland Slue	٧ الرام	WINSTO	-M.EM // /	The said
From To Ft		AIRPO	5 //	you H
SCREEN:	ndship.			98 30
			698	3
Depth Diameter Slot Size Material		890		
From 9.5 To24.5 Ft. 2 in 0.010 in PVC	$i \subseteq i$	A CONTRACTOR OF THE PARTY OF TH	// 0	A STORY
From To Ft in in	a C	2)11		
From To Ft in in	377	//> ?	1, 1,	05
GRAVEL PACK:		77/	~	2 2
Openth Size Material	القسريرا			89/1/201
From 7.5 To 24.5 Ft. Fine Filer Sand				
FromToFtFt	7/10	11/1		900
	. 1			· × × ~ ~
I DO HEREBY CERTIFY THAT THIS WELL WAS CONSTRUCTED STANDARDS, AND THAT A COPY OF THIS RECORD WAS BEEN PER	IN ACCORD	ANCE WITH	1 15 NCAC 2C.	WELL CONSTRUCTION
y. ozol	Pa	\sim		05/02/91

SIGNATURE OF CONTRACTOR OR AGENT

Submit original to Division of Environmental Management and copy to well owner.



BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1,4 IN. 1.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE

50 % ROCK CORE RECOVERY

LOSS OF DRILLING WATER



TEST BORING RECORD

BORING NO. MW-4

DATE DRILLED 04/10/91

JOB NO. 015/91/036

NORTH CAROLINA DEPARTMENT OF NATURAL RESOURCES AND COMMUNITY DEVELOPMENT DIVISION OF ENVIRONMENTAL MANAGEMENT - GROWNWATER SECTION
P.G. 80X 27687 - RALEIGHULG. 27811, PHONE (919) 702-5083

₩	ELL	CONS	TRUC	MOIT	RECO	ORD
---	-----	------	------	------	------	-----

1 Revised 11/84


	FOR OFFICE USE ONLY
Quad. No	Senal No.
Lat.	Lang Ps
Minor Basin _	
Basin Code _	
Header Ent	GW-1 Ent

CATE

		Header	Ent GW-1 Ent
DRILLING CONTRACTOR TRIGON ENGINEERING CONSULTANTS,	INC.	·	
DRILLER REGISTRATION NUMBER 813	21416		CONSTRUCTION ER: 40-0949-WM-0336
WELL LOCATION: (Show sketch of the location below)			
Nearest Town: Greensboro	Caunty: _	Guilfo	rd County
(Road, Community, or Supplyision and Lot No.)	Ceat	n	DRILLING LOG
OWNER Piedmont Triad Airport Authority	FromMW-4	Ta	Formation Description
ADDRESS P.O. Box 35005		10.5	Asphalt Rubble
Greensboro, NC (Street or Route No., 27425	10.5	15.5	Soft Grey Black Slightly
City or Town State Zio Code . DATE DRILLED 04/10/91 USE OF WELL Monitoring	15.5	21.0	Fine Sandy Silty CLAY-Alluvia Partially Weathered Rock
TOTAL DEPTH 20.5 CUTTINGS COLLECTED $ ext{M}$ Yes $ ext{C}$ No			Samples As Green White Medium
DOES WELL REPLACE EXISTING WELL? Tyes VI No			to Fine Sandy SILT-Residual
STATIC WATER LEVEL: 10.9 FT. I above TOP OF CASING. TOP OF CASING IS FT. ABOVE LAND SURFACE.			
			
YIELD (cpm): N/A METHOD OF TEST N/A			
WATER ZONES (death): 8.8			·
CHLORINATION: Type N/A Amount N/A	:		
CASING:			
Wall Thickness Deom Clameter or Weignt/St Marerial	If a	dditional s	pace is needed use back of form.
Osom Clameter of Weight/St. Material 2.0 SCH40 PVC	(Chau dies		LOCATION SKETCH
FromToFt	Candw cire	isa tajatat isagu and	distance from at least two State Roads.
FramTa		المركز ك	
. GROUT:	idship Ch		
Oeom Material Memod 7	77	WINSTO	REM //
rrgm 1a		AIRPORT	Hors.
SCREEN:	Endship	X//	
	200	es) × (.	
Depth Diameter Slot Size Material From 5.5 To 20.5 Ft. 2.0 in. 0.010 in. PVC		secon .	
From To Ft in in.		26:0	
Fram Ta Ft in in	الراكمة	15	
GRAVEL PACK:		آج	250
Genth Size Material S			BM () (200)
FromToFt. Fine Filter Sand		نجبر	>> MANAGEMENT
FramTaFt	710/	1//	
ASMARKS: Bentonite Seal From 2.5' to 3.5'	(() / .	11/6/6	
I DO HEREBY CERTIFY THAT THIS WELL WAS CONSTRUCTED I STANDARDS, AND THAT A COPY OF THIS RECORD HAS BEEN REC	N ACCORDAN	METT OM	15 NCAC 2C. WELL CONSTRUCTION NER. 05/02/91

SONATURE OF CONTRACTOR OR AGENT

Submit onginal to Division of Environmental Management and cody to well owner.




BORING AND SAMPLING MEETS ASTM D-1586 CORE DRILLING MEETS ASTM D-2113

PENETRATION IS THE NUMBER OF BLOWS OF 140 LB. HAMMER FALLING 30 IN. REQUIRED TO DRIVE 1.4 IN. I.D. SAMPLER 1 FT.

UNDISTURBED SAMPLE

50 % ROCK CORE RECOVERY

■ LOSS OF DRILLING WATER



TEST BORING RECORD

BORING NO.

DATE DRILLED

JOB NO.

04/11/91 015-91-036

NORTH CARGUNA DEPARTMENT OF NATURAL RESOURCES AND COMMUNITY DEVELOPMENT DIVISION OF ENVIRONMENTAL MANAGEMENT - GROUNOWATER SECTION
P.O. BOX 27687 - RALEIGHLAC. 27611, PHONE (919) 733-5083

WELL	CONST	RUCT	NOF	RECO	RD
------	-------	------	-----	------	----

1 Revised 11/84

	FOR OFFICE USE ONLY
Quad. No	Sensi No.
Lat.	Long Po
Minor Basin _	
Header Ent	GW-1 Ent

CATE

er Ent GW-1 Ent
CONSTRUCTION BER: 40-0949-WM-0336
ord County
. ORILLING LOG
Formation Description
Grass and Topsoil
Stiff Tan Brown Slightly Claye
Coarse to Fine Sandy SILT-Fill
Stiff Tan Orange and Brown Slightly Micaceous Fine Sandy
SILT-Fill
Firm to Stiff Black Brown and
Grey Medium to Fine Sandy Silt
CLAY-Alluvial
Very Stiff Tan Orange and Brow
Medium to Fine Sandy SILT-
Residual
space is needed use back of form.
LOCATION SKETCH
nd distance from at least two State Roads.
and July and
O HIGH JOINT
PORT
Dog Bay 19 Hor
000
0 1967
950
BM (3880)
83 - BM 12 - 12 - 12 - 12 - 12 - 12 - 12 - 12
1000
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \

SIGNATURE OF CONTRACTOR OR AGENT

Submit anginal to Division of Environmental Management and copy to well owner.

APPENDIX C



ENVIRONMENTAL LABORATORIES, INC. 11104 DOWNS ROAD PINEVILLE, NC 28134 704/ 588-5076 FAX 704/ 588-2454

NC Certification Number: 305 SC Certification Number: 99032

Date of Report:
Date Received:

April 26, 1991 April 10, 1991

Approved By:____

James C. Taylor

General Manager

Client: Trigon Engineering

P.O. Box 18846

Greensboro, North Carolina 27419-8846

Contact: Scott Pearce

Customer Number: 2021

LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT
826A1	B-3S	Arsenic	<0.005	mg/l
		Selenium	<0.005	mg/1
		Cadmium	<0.01	mg/1
		Chromium	<0.05	mg/1
		Lead	<0.05	mg/1
		Mercury	<0.001	mg/1
		Silver	<0.01	mg/1
		Barium	<0.50	mg/l
826A2	B-3W	Total Petroleum Hydrocarbons by Method 3550	<10	mg/kg
		Total Petroleum Hydrocarbons by Method 5030	9	mg/kg
826A3 B-3N	Total Petroleum Hydrocarbons by Method 3550	<10	mg/kg	
		Total Petroleum Hydrocarbons by Method 5030	<1	mg/kg

	LABORATORY REPORT				
LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT	
826A4	B-3S	Total Petroleum Hydrocarbons by Method 3550	<10	mg/kg	
		Total Petroleum Hydrocarbons by Method 5030	<1	mg/kg	
826A5	B-3E	Total Petroleum Hydrocarbons by Method 3550	<10	mg/kg	
		Total Petroleum Hydrocarbons by Method 5030	<1	mg/kg	
826A6	B-3W EX	Total Petroleum Hydrocarbons by Method 3550	<10	mg/kg	
		Total Petroleum Hydrocarbons by Method 5030	<1	mg/kg	
826A7	MW-2	Total Petroleum Hydrocarbons by Method 3550	<10 ¹ 4 (mg/kg	
		Total Petroleum Hydrocarbons by Method 5030	<1	mg/kg	
826A8	HA-1, HA-2	Cyanide, Total Phenol Arsenic Selenium Cadmium Chromium Copper Lead Nickel Zinc Mercury Silver Antimony	<0.01 <0.25 <0.005 <0.005 <0.01 4.30 22.6 13.3 3.95 27.5 <0.001 <0.01	mg/1 mg/1 mg/1 mg/1 mg/1 mg/1 mg/1 mg/1	

LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT
826A8	HA-1,HA-2	Beryllium	<0.01	mg/l
		Thallium	<0.5	mg/1
		4-NITROPHENOL	<100	ug/kg
		PENTACHLOROPHENOL	<100	
		4,6-DINITRO-O-CRESOL	<100	
		2,4-DINITROPHENOL	<100	
		4-CHLORO-3-METHYPHEN	OL <100	
		2,4,6-TRICHLOROPHENO	L <100	
		2,4-DICHLOROPHENOL	<100	
		2,4-DIMETHYLPHENOL	<100	
		2-NITROPHENOL	<100	
		2-CHLOROPHENOL	<100	
		N-NITROSODIMTHYLAMIN	E <100	
		BIS(2-CHLOROETHYL)ET	HER <100	
		N-NITROSO-DI-N-PROPY	LAMINE<100	
		NITROBENZENE	<100	
		HEXACHLOROBUTADIENE	<100	ug/kg
		1,2,4-TRICHLOROBENZE	NE <100	
		ISOPHORONE	<100	
		NAPHTHALENE	<100	
		BIS(2-CHLOROETHOXY)	METHANE<10	Oug/kg
		HEXACHLOROCYCLOPENTA	DIENE <100	ug/kg
		2-CHLORONAPHTHALENE	<100	
		ACENAPHTHYLENE	<100	
		ACENAPHTHENE	<100	
		DIMETHYL PHTHALATE	<100	ug/kg
		2,6-DINITROTOLUENE	<100	ug/kg
		FLUORENE	<100	
		4-CHLOROPHENYL PHENY	L ETHER<10	
		2,4-DINITROTOLUENE	<100	ug/kg
		DIETHYL PHTHALATE	<100	ug/kg
		N-NITROSODIPHENYLAMI	NE <100	ug/kg
		1,2-DIPHENYL HYDRAZI	NE <100	ug/kg
		HEXACHLOROBENZENE	<100	ug/kg
		4-BROMOPHENYL PHENYL	ETHER <10	0ug/kg
		PHENANTHRENE	<100	ug/kg
		ANTHRACENE	<100	ug/kg
		DI-N-BUTLY-PHTHALATE	<100	ug/kg
		PLUORANTHENE	<100	ug/kg
		PYRENE	<100	
		BENZIDENE	<100	
		BUTYL BENZYL PHTHALA		ug/kg
		BIS(2-ETHYLHEXYL) PH	THALATE<10	0ug/kg
		BENZO (a) ANTHRACENE		
	•	CHRYSENE	<100	

Trigon Engineering April 26, 1991 Page 4

LAB ID	SAMPLE ID	PARAMETER R	ESULT	UNIT
326A8	HA-1,HA-2	3,3'-DICHLOROBENZIDIN	E <100	
		DI-N-OCTYL PHTHALATE	<100	
		BENZO (b) FLUORANTHEN	E <100	ug/kg
		BENZO (k) FLUORANTHEN		
		BENZO (a) PYRENE	<100	
		INDENO (1,2,3-CD) PYR		
		DIBENZ (a,h) ANTHRACE	NE <100	ug/kg
		BENZO (g,h,i,) PERYLE		
		2-METHYLNAPHTHALENE	<100	ug/kg
		BIS(2-CHLOROISOPROPYL) ETHER	
•			<100	ug/kg
		4-CHLOROPHENYL PHENYL	ETHER	
			<100	
		HEXACHLOROETHANE	<100	
		ALDRIN	<100	
		A-BHC	<100	
		B-BHC	<100	
		C-BHC	<100	
		D-BHC	<100	
		CHLORODANE	<100	
		4,4-DDD	<100	
		4,4-DDE	<100	
		4,4-DDT	<100	
		DIELDRIN	<100	
		ENDOSULFAN I	<100	
		ENDOSULFAN II	<100	
		ENDOSULFAN SULFATE	<100	
		ENDRIN	<100	
		ENDRIN ALDEHYDE	<100	
		HEPTOCHLOR	<100	
		HEPTOCHLOR EPOXIDE	<100	• •
		TOXAPHENE	<100	ug/k
		PCB-1016	<100	ug/k
		PCB-1221	<100	ug/k
		PCB-1232	<100	ug/k
		PCB-1242	<100	ug/k
		PCB-1248	<100	ug/k
		PCB-1254	<100	ug/k
		PCB-1260	<100	ug/k
		Benzene	239	ug/k
		Bromodichloromethane	<100	ug/k
		Bromoform	<100	ug/k
		Bromomethane Carbon Tetrachloride	<100	ug/k
		Carpon Petrachloride	<100	ug/k

LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT
826A8	HA-1,HA-2	Chloroethane	<100	ug/kg
	•	2-Chloroethylvinyl E	ther <100	
		Chloroform	<100	ug/kg
		Chloromethane	<100	
		Dibromochloromethane	<100	
		1,2-Dichlorobenzene	<100	ug/kg
		1,3-Dichlorobenzene	<100	ug/kg
		1,4-Dichlorobenzene	<100	
		Dichlorodifluorometh	ane <100	
		1,1-Dichloroethane	<100	ug/kg
		1,2-Dichloroethane	<100	
		1,1-Dichloroethene	<100	
		Trans-1,2-Dichloroet	hene <100	ug/kg
		1,2-Dichloropropane	<100	ug/kg
		Cis-1,3-Dichloroprop	ene <100	ug/kg
		Trans-1,3-Dichloropr	opene<100	ug/kg
		Ethylbenzene	<100	ug/kg
		Methylene Chloride	<100	ug/kg
		1,1,2,2-Tetrachloroe	thane<100	ug/kg
		Tetrachloroethene	<100	ug/kg
		Toluene	246	ug/kg
		1,1,1-Trichloroethan	e 206	
		1,1,2-Trichloroethan	e <100	ug/kg
		Trichloroethene	<100	ug/kg
		Trichlorofluorometha	ne <100	ug/kg
		Xylene	<100	ug/kg



ENVIRONMENTAL LABORATORIES, INC. 11104 DOWNS ROAD PINEVILLE, NC 28134 704/ 588-5076 FAX 704/ 588-2454

NC Certification Number: 305 SC Certification Number: 99032

Date of Report: April 26, 1991
Date Received: April 16, 1991

Approved By:_

James C. Taylor General Manager

Client: Trigon Engineering

P.O. Box 18846

Greensboro, North Carolina 27419-8846

Contact: Scott Pearce

Customer Number: 2021

LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT
851A1	BP-1	Total Petroleum Hydrocarbons by Method 3550	14302	mg/kg
		Total Petroleum Hydrocarbons by Method 5030	971	mg/kg
851A2	BP-2	Total Petroleum Hydrocarbons by Method 3550	2044	mg/kg
		Total Petroleum Hydrocarbons by Method 5030	221	mg/kg
851A3	BP-2	Arsenic Selenium Cadmium Chromium Lead Mercury Silver Barium	<0.005 <0.005 <0.01 <0.05 <0.05 <0.001 <0.01	mg/l mg/l mg/l mg/l mg/l mg/l mg/l

		LABORATORY REPORT		
LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT
851A4 BI	BP-3	Total Petroleum Hydrocarbons by Method 3550	40	mg/kg
		Total Petroleum Hydrocarbons by Method 5030	<1	mg/kg
851A5	FD-HA	Total Petroleum Hydrocarbons by Method 3550	<10	mg/kg
		Total Petroleum Hydrocarbons by Method 5030	<1	mg/kg
851A6	STB-1	Total Petroleum Hydrocarbons by Method 3550	10	mg/kg
		Total Petroleum Hydrocarbons by Method 5030	<1	mg/kg
851A7	STB-2	Total Petroleum Hydrocarbons by Method 3550	11	mg/kg
		Total Petroleum Hydrocarbons by Method 5030	<1	mg/kg
851A8 STB-3	STB-3	Total Petroleum Hydrocarbons by Method 3550	<10	mg/kg
		Total Petroleum Hydrocarbons by Method 5030	<1	mg/kg
851A9	MW-3	Total Petroleum Hydrocarbons by Method 3550	<10	mg/kg

	LABORATORY REPORT				
LAB ID	SAMPLE ID	PARAMETER	RESULT	ľ	UNIT
851A9	MW-3	Total Petroleum Hydrocarbons by Method 5030	54		mg/kg
851A10	MW-5	Total Petroleum Hydrocarbons by Method 3550	<10		mg/kg
		Total Petroleum Hydrocarbons by Method 5030	<1		mg/kg
851A11	B-20S	Total Petroleum Hydrocarbons by Method 3550	<10		mg/kg
		Total Petroleum Hydrocarbons by Method 5030	<1		mg/kg
851A12	B-20N	Total Petroleum Hydrocarbons by Method 3550	<10		mg/kg
		Total Petroleum Hydrocarbons by Method 5030	<1		mg/kg
851A13	MW-1	Total Petroleum Hydrocarbons by Method 3550	5.0	i.	mg/l
		Total Petroleum Hydrocarbons by Method 5030	<0.1		mg/l
		Benzene Bromodichlorometha Bromoform Bromomethane Carbon Tetrachlori Chlorobenzene Chloroethane 2-Chloroethylvinyl Chloroform	de	<1 <1 <1 <1 <1 <1 <1 <1 <1 <1 <1 <1 <1 <	ug/l ug/l ug/l ug/l ug/l ug/l ug/l ug/l

LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT
851A13	MW-1	Chloromethane	<1	ug/l
0021120	2377	Dibromochloromethane	-	ug/l
		1,2-Dichlorobenzene	<1	ug/l
		1,3-Dichlorobenzene	<1	ug/l
		1,4-Dichlorobenzene	<1	ug/l
		Dichlorodifluorometh		ug/1
		1,1-Dichloroethane	<1	ug/1
		1,2-Dichloroethane	<1	ug/1
		1,1-Dichloroethene	<1	ug/l
		Trans-1,2-Dichloroet		ug/l
		1,2-Dichloropropane	<1	ug/l
		Cis-1,3-Dichloroprop		ug/l
		Trans-1,3-Dichloropr		ug/l
		Ethylbenzene	<1	ug/l
		Methylene Chloride	<1	ug/l
		1,1,2,2-Tetrachloroe		ug/l
		Tetrachloroethene	<1	ug/l
		Toluene	<1	ug/l
		1,1,1-Trichloroethan		ug/l
		1,1,2-Trichloroethan		ug/1
		Trichloroethene	<1	ug/1
		Trichlorofluorometha		ug/l
		Xylene	<1	ug/l
		Arsenic	<0.005	mg/1
		Selenium	<0.005	mg/1
		Cadmium	<0.01	mg/1
		Chromium	<0.05	mg/1
		Lead	<0.05	mg/1
		Mercury	<0.001	mg/1
		Silver	<0.01	mg/1
		Barium	<0.5	mg/l
851A14	MW-2	Total Petroleum Hydrocarbons by	3.0	mg/l
		Method 3550		
		Total Petroleum Hydrocarbons by Method 5030	<0.1	mg/l
		Benzene	<1	ug/l
		Bromodichloromethane	<1	ug/l
		Bromoform	<1	ug/l
		Bromomethane	<1	ug/l

LAB ID	SAMPLE ID	PARAMETER	RESULT	•	UNIT
851A14	MW-2	Carbon Tetrachlorid	e	<1	ug/l
		Chlorobenzene		<1	ug/1
		Chloroethane		<1	ug/l
		2-Chloroethylvinyl	Ether	<1	ug/l
		Chloroform		34	ug/l
		Chloromethane		<1	ug/l
		Dibromochloromethan	e	<1	ug/1
		1,2-Dichlorobenzene		<1	ug/l
		1,3-Dichlorobenzene		<1	ug/1
		1,4-Dichlorobenzene		<1	ug/l
		Dichlorodifluoromet	hane	<1	ug/l
		1,1-Dichloroethane		<1	ug/l
		1,2-Dichloroethane		<1	ug/l
		1,1-Dichloroethene		<1	ug/l
		Trans-1,2-Dichloroe	thene	<1	ug/l
		1,2-Dichloropropane		<1	ug/l
		Cis-1,3-Dichloropro	pene	<1	ug/l
		Trans-1,3-Dichlorop	ropene	<1	ug/l
		Ethylbenzene		<1	ug/l
		Methylene Chloride		<1	ug/1
		1,1,2,2-Tetrachloro	ethane	<1	ug/1
		Tetrachloroethene		<1	ug/1
		Toluene		258	ug/l
		1,1,1-Trichloroetha	ne	<1	ug/1
		1,1,2-Trichloroetha	ne	<1	ug/l
		Trichloroethene		<1	ug/l
		Trichlorofluorometh	ane	<1	ug/l
		Xylene		<1	ug/1
		Arsenic	<0.005	i .	mg/1
		Selenium	<0.005	,	mg/1
		Cadmium	<0.01		mg/1
		Chromium	<0.05		mg/1
		Lead	<0.05		mg/1
		Mercury	<0.001	•	mg/1
		Silver	<0.01		mg/I
		Barium	<0.5		mg/1
851A15	MW-3	Total Petroleum	<1.0		mg/l
		Hydrocarbons by			
		Method 3550			
		Total Petroleum	4.0		mg/l
		Hydrocarbons by			
		Method 5030			

LABORATORY REPORT

LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT
851A15	MW-3	Benzene	356	ug/l
		Bromodichloromethan	e <1	ug/1
		Bromoform	<1	ug/l
		Bromomethane	<1	ug/l
		Carbon Tetrachlorid	e <1	ug/l
		Chlorobenzene	<1	ug/l
		Chloroethane	<1	ug/1
		2-Chloroethylvinyl	Ether <1	ug/l
		Chloroform	38	ug/1
		Chloromethane	<1	ug/l
		Dibromochloromethan		ug/1
		1,2-Dichlorobenzene		ug/l
		1,3-Dichlorobenzene		ug/1
		1,4-Dichlorobenzene		ug/1
		Dichlorodifluoromet		ug/l
		1,1-Dichloroethane	<1	ug/l
		1,2-Dichloroethane	<1	ug/l
		1,1-Dichloroethene	<1	ug/l
		Trans-1,2-Dichloroe		ug/l
		1,2-Dichloropropane		ug/l
		Cis-1,3-Dichloropro	_	ug/l
		Trans-1,3-Dichlorop		ug/l
		Ethylbenzene	<1	ug/l
		Methylene Chloride	<1	ug/l
		1,1,2,2-Tetrachloro		ug/l
		Tetrachloroethene	363	ug/1
		Toluene	988	ug/l
		1,1,1-Trichloroetha		ug/1
		1,1,2-Trichloroetha Trichloroethene	ne <1 <1	ug/l
		Trichlorofluorometh		ug/l ug/l
		Xylene	286	ug/l
		Arsenic	<0.005	mg/l
		Selenium	<0.005	mg/1
		Cadmium	<0.01	mg/1
		Chromium	<0.05	mg/l
		Lead	<0.05	mg/1 g/l
		Mercury	<0.001	mg/1
		Silver	<0.01	mg/1
		Barium	<0.5	mg/1
851A16	MW-4	Total Petroleum Hydrocarbons by Method 3550	1.0	mg/l

LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT
851A16	MW-4	Total Petroleum Hydrocarbons by Method 5030	<0.1	mg/l
		Benzene Bromodichlorometh Bromoform Bromomethane Carbon Tetrachlor Chlorobenzene Chloroethane 2-Chloroethylviny Chloroform Chloromethane Dibromochlorometh 1,2-Dichlorobenze 1,3-Dichlorobenze 1,4-Dichlorobenze Dichlorodifluorom 1,1-Dichloroethan 1,2-Dichloroethan 1,2-Dichloroethan 1,1-Dichloroethan 1,2-Dichloroethan 1,1-Dichloroethan 1,1-Dichloroethan 1,1-Dichloroethan 1,1-Dichloroethan 1,1-Dichloroethan 1,2-Dichloroethan	Column C	ug/1 ug/1 ug/1 ug/1 ug/1 ug/1 ug/1 ug/1
		Methylene Chlorid 1,1,2,2-Tetrachlo Tetrachloroethene Toluene 1,1,1-Trichloroet 1,1,2-Trichloroet Trichloroethene Trichlorofluorome Xylene Arsenic Selenium Cadmium Chromium Lead Mercury Silver Barium	roethane <1	ug/1 ug/1 ug/1 ug/1 ug/1 ug/1 ug/1 ug/1

LA	R	an	ħ	TT/	75	V	DEE	ORT
ц	יכבו	\mathbf{u}			JI		NE-F	URI

LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT
851A17	MW-5	Total Petroleum Hydrocarbons by Method 3550	1.0	mg/l
		Total Petroleum Hydrocarbons by Method 5030	<0.1	mg/l
		Benzene	<1	ug/l
		Bromodichlorometh	-	ug/l
		Bromoform	<1	ug/1
		Bromomethane	<1	ug/l
		Carbon Tetrachlor		ug/l
		Chlorobenzene	<1	ug/l
		Chloroethane	<1	ug/l
		2-Chloroethylviny		ug/1
		Chloroform Chloromethane	8 <1	ug/l
		Dibromochlorometh		ug/1
		1,2-Dichlorobenze		ug/l ug/l
		1,3-Dichlorobenze		ug/l
		1,4-Dichlorobenze		ug/l
		Dichlorodifluorom		ug/l
		1,1-Dichloroethan		ug/l
		1,2-Dichloroethan		ug/1
		1,1-Dichloroethen		ug/1
		Trans-1,2-Dichlor		ug/l
		1,2-Dichloropropa		ug/l
		Cis-1,3-Dichlorop		ug/l
	•	Trans-1,3-Dichlor		ug/l
		Ethylbenzene	<1	ug/1
		Methylene Chlorid	le 610	ug/1
		1,1,2,2-Tetrachlo	roethane <1	ug/l
		Tetrachloroethene	· <1	ug/l
		Toluene	248	ug/l
		1,1,1-Trichloroet		ug/1
		1,1,2-Trichloroet		ug/1
		Trichloroethene	<1	ug/1
		Trichlorofluorome		ug/1
		Xylene	<1	ug/l
		Arsenic	<0.005	mg/l
		Selenium	<0.005	mg/l
		Cadmium	<0.01	mg/1
		Chromium	<0.05	mg/1
		Lead	<0.05	mg/1

		-	-	
LAB ID	SAMPLE ID	PARAMETER	RESULT	UNIT
851A17	MW-5	Mercury	<0.001	mg/1
		Silver	<0.01	mg/1
		Barium	<0.5	mg/l
851A18	MW-4 F.B.	Benzene	<1	ug/l
		Bromodichloromethane	_	ug/1
		Bromoform	<1	ug/l
		Bromomethane	<1	ug/l
		Carbon Tetrachloride	<1	ug/l
		Chlorobenzene	<1	ug/l
		Chloroethane	<1	ug/1
		2-Chloroethylvinyl E	ther <1	ug/l
		Chloroform	8	ug/1
		Chloromethane	<1	ug/1
		Dibromochloromethane	<1	ug/1
		1,2-Dichlorobenzene	<1	ug/l
		1,3-Dichlorobenzene	<1	ug/l
		1,4-Dichlorobenzene	<1	ug/1
		Dichlorodifluorometh	ane <1	ug/1
		1,1-Dichloroethane	<1	ug/l
		1,2-Dichloroethane	<1	ug/1
		1,1-Dichloroethene	<1	ug/1
		Trans-1,2-Dichloroet	hene <1	ug/l
		1,2-Dichloropropane	<1	ug/l
		Cis-1,3-Dichloroprop	ene <1	ug/1
		Trans-1,3-Dichloropr	opene <1	ug/l
		Ethylbenzene	<1	ug/l
		Methylene Chloride		ug/1
		1,1,2,2-Tetrachloroe		ug/l
		Tetrachloroethene	<1	ug/l
		Toluene	247	
		1,1,1-Trichloroethan		ug/l
		1,1,2-Trichloroethan		ug/l
		Trichloroethene	<1	ug/l
		Trichlorofluorometha		ug/l
		Xylene	<1	ug/l

